

## Specifications

### General Specifications

<b>Interface</b>	<b>USB Port:</b> <b>Hi-Speed USB *</b>  <b>* A computer that complies with Hi-Speed USB standard is required. Since the Hi-Speed USB interface is fully upwardly compatible with USB 1.1, it can be used at USB 1.1.</b>
<b>Operating environment</b>	<b>Temperature: 41 to 95 °F (5 to 35 °C)</b> <b>Humidity: 10 to 90 % RH (no condensation)</b>  <b>* The performance of the printer may be reduced under certain temperature and humidity conditions.</b>  <b>Recommended conditions:</b> <b>Temperature: 59 to 86 °F (15 to 30 °C)</b> <b>Humidity: 10 to 80 % RH (no condensation)</b>  <b>* For the temperature and humidity conditions of papers such as photo paper, refer to the paper's packaging or the supplied instructions.</b>
<b>Storage environment</b>	<b>Temperature: 32 to 104 °F (0 to 40 °C)</b> <b>Humidity: 5 to 95 % RH (no condensation)</b>
<b>Power supply</b>	<b>AC 100-240 V, 50/60 Hz</b>  <b>(The supplied power cord is only for the country or region you purchased.)</b>
<b>Power consumption</b>	<b>Printing (Copy): 18 W or less *1</b> <b>Standby (minimum): 0.6 W or less *1*2</b> <b>Standby (all ports connected): 0.6 W or less</b> <b>OFF: 0.2 W or less</b>  <b>*1 USB connection to a PC</b> <b>*2 The wait time for standby cannot be changed.</b>

<b>External dimensions (W x D x H)</b>	<b>Approx. 17.6 x 13 x 6.6 in. (Approx. 445 x 330 x 167 mm)</b> <b>* With the trays retracted.</b>
<b>Weight</b>	<b>Approx. 14.0 lb (Approx. 6.4 kg)</b> <b>* With the Print Head installed.</b>

#### **Scan Specifications**

<b>Scanner driver</b>	<b>Windows: TWAIN 1.9 Specification, WIA</b>
<b>Maximum scanning size</b>	<b>A4/Letter, 8.5 x 11.7 in. (216 x 297 mm)</b>
<b>Optical resolution (horizontal x vertical)</b>	<b>600 x 1200 dpi *</b> <b>* Optical Resolution represents the maximum sampling rate based on ISO 14473.</b>
<b>Gradation (Input / Output)</b>	<b>Gray: 16 bit/8 bit</b> <b>Color: RGB each 16 bit/8 bit</b>